

Holes in Pool Render Surface

Appearance

- Small area has become dislodged.

Possible Causes

- Picking out a piece of aggregate or scraping a nodule off the surface which caused a larger section to come out.
- During water blasting a small amount of product was dislodged.
- Spike marks left in surface by applicator during installation.
- Pole vaulting – using a pool pole like a pogo stick creating a hole.

Possible Remedies

Option 1

- Mix a waterproof epoxy or acrylic or rapid setting waterproof binding agent with matching oxide or original cement Aristone render and fill the hole.

Option 2

- Mix matching Aristone with an acrylic and fill the hole.